

WIN THE LOTO:

Secure Your Investment and Worker Safety with a Lockout/Tagout (LOTO) Procedure.

AVOID

STIFF FINES:
\$7,000,000
in potential fines for a company with 100 machines and no LOTO

AVOID

LAWSUITS:
\$10,000,000
or more in potential civil lawsuits

AVOID

LOST TIME:
24 LOST DAYS
on avg. before returning to work from any potential injury

LEARN THE LOTO SEQUENCE



8. COMPLETE

The machine or equipment is now locked out.

7. VERIFY

Verify energy has been dissipated and the machine will not operate.

6. DISSIPATE

Stored or residual energy must be dissipated or restrained.

5. LOCKOUT

Lockout the energy isolating device(s) with assigned individual locks.

1. NOTIFY

Notify affected employees machinery will be shutdown and locked out.

2. IDENTIFY

Identify the type and magnitude of the energy that the machine utilizes.

3. SHUTDOWN

Shut down machinery by the normal stopping procedure.

4. DEACTIVATE

Isolate machine by deactivating the energy isolating device(s).

WHO NEEDS TRAINING?



AUTHORIZED

Operators and employees who actually lock and tag machines



AFFECTED

Employees who work around machines that require LOTO



ALL OTHERS

Office or administration personnel who might be exposed to machines

Learn how you can mitigate the risk by incorporating a customized lockout/tagout program for your worksite.

GIVE US A CALL:

877-348-4975

Find out more at: wellworkforce.com

“THE FUTURE IS PREVENTION. THE FUTURE IS NOW.”

Fit For Work is an established national provider of innovative workplace injury prevention services that has unmatched expertise and sustainability.

